



## ViewScan Travel Case Guide

**ViewScan Parts List:**

- 4x Leveling screws for feet
- 4x Large thread wing screw for legs
- 4x Wing screws with spacers for camera boom
- 4x Cut wing screw for cross bar
- 4x Silver thumb screw for monoliths
- 1x Data cable for cross bar connection
- 3x Ethernet patch cables
- 1x Laptop
- 1x Laptop power supply
- 1x PoE switch
- 1x PoE switch power supply
- 2x ViewScan monolith pillars
- 2x ViewScan feet
- 1x ViewScan brace crossbar bottom channel
- 1x ViewScan brace crossbar cover
- 1x ViewScan power supply
- 1x PoE camera
- 1x Camera boom
- 1x Traveling case



- The large rectangular cutout is for both pillars with foam sheet separator.



- The cutout next to the pillars is for the camera boom.



- The cutout next to the camera boom is for the crossbar





- Use this space for ViewScan accessories:
  - Ethernet patch cables
  - Switch with power supply
  - Laptop power supply
  - ViewScan power supply
  - Hardware



- The laptop will sit above the accessories in this dedicated area. Cover the laptop with the foam sheet to protect it from damage.



- Use this cutout for the handheld metal detector



- Slide the feet between the foam and plastic to ensure there is no movement when traveling.



- Fasten all 6 latches before use.

